Idaho PUC Pipeline Safety Inspection Summary

| Inspector(s): | pector(s): Ulmer/Perkins/Russo | | Date(s): | Sept 30-Oct 1, 2019 |
|--|--------------------------------|------------------------------|-----------------|---------------------|
| C | Namela | ant Can Dunancium | Unit/OPID: | 25223 |
| Company/Owner: | Northwe | est Gas Processing | Unit/OPID: | 25223 |
| Inspection Type 9 Time /1 | day 0 E day) | Total In | spection Days: | 8 |
| Inspection Type & Time (1 | day, 0.5 day) | Total II | ispection Days. | 0 |
| Standard: 8 Construction: | Training: | (T)(D) Integrity Management: | Incident: | |
| M/M: Follow-up: | OQ: | Damage Prevention: | D&A: | |
| Inspection Summary | | | | |
| 2019 Records Audit Northwest Gas Processing | | | | |
| September 27, 2019: (1 Standard prep) | | | | |
| Prepared for the Northwest Gas Processing records and field inspection through review of the PHMSA | | | | |
| inspections Forms and 2018 inspection results. The company's pipeline system in Idaho consists of transmission | | | | |
| and gathering lines. | | | | |
| | | | | |
| September 30, 2019: (3 Standard) | | | | |
| Darrin Ulmer, Bruce Perkins and Kyle Russo of the Idaho Public Utilities Commission met with NWGP's plant | | | | |
| manager at the Hwy 30 plant in New Plymouth, ID to review records for the previous year. PHMSA Forms were | | | | |
| used as a guide throughout the audit to ensure all areas were completed as they pertain to required records and | | | | |
| procedures. | | | | |
| procedures. | | | | |
| October 1, 2019: (3 Standard) The field portion of the audit was conducted at NWGP's Hwy 30 plant, little Willow Station and valve sites to | | | | |
| ensure compliance with field requirements. | | | | |
| Oh | | | | |
| Observations: | | | | |
| Went to take the rectifier reading at Little Willow and noticed the rectifier was off. When asked why, the tech | | | | |
| stated he must have left it off the last time he was up taking readings the previous month (Aug). | | | | |
| Noted casing vent needed paint and a few carsonites were down. | | | | |
| | | | | |
| October 2, 2019: (1 Standard) | | | | |
| Wrote the inspection report, completed PHMSA and IPUC audit forms and attached inspection documents. | | | | |
| Attached. | | | | |
| Attached: | | | | |
| IPUC Form 3. Full Intention | | | | |
| IPUC Form 3, Exit Interview | | | | |
| IPUC Field Equipment Status Worksheets | | | | |
| Corrective Action Required: | | Yes | X No | |
| Follow-up Required: | by (date): | 2020 Inspection Yes | | |
| the same of the sa | by (date). | 2020 Hispection 1es | | |
| Inspector (Lead): | the | | Date: Zocl | 2019 |
| Reviewer: | Stanta | <u> </u> | Date: | 1 20 / 0 |
| a jack | 170110 | | 3 000 | + 2019 |